RAJALAKSHMI GEO CONSULTANTS

Rukmini Nagar, Nagasandra, Tumkur road, Bangalore 560057
Mobile: 9986028766

DATE: 19/07/21

REPORT ON GROUND WATER INVESTIGATION

01. Name of the Party	**Executive Engineer, BBMP, Dasarahalli Division.**
02. Location of land/Site	w no 14 siddeswara layout siddedahalli
03. Purpose of Ground Water	Drinking water
04. Area	Bagalagunte
05. Approximate Drilling Depth	380-400 rmt
06. Approximate Casing Pipe	50-60 rmt
07. PVC Pipe	20-25 rmt
08. Expected Yield	1500-2000 GPH
10. Remarks	

Note: Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಡಿ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿ.ಬಿ.ಎಂ.ಪಿ
ಬೆಂಗಳೂರು-560073

Rajalakshmi
Geo Consultants
Bangalore

Scanned with CamScanner

RAJALAKSHMI GEO CONSULTANTS

Rukmini Nagar, Nagasandra, Tumkur road, Bangalore 560057
Mobile: 9986028766

DATE: 19/07/21

REPORT ON GROUND WATER INVESTIGATION

01. Name of the Party	**Executive Engineer, BBMP, Dasarahalli Division.**
02. Location of land/Site	w no 14 swandary layout 1 st main road near circala siddedahalli
03. Purpose of Ground Water	Drinking water
04. Area	Bagalagunte
05. Approximate Drilling Depth	390-400 rmt
06. Approximate Casing Pipe	50-60 rmt
07. PVC Pipe	20-25 rmt
08. Expected Yield	1500-1800 GPH
10. Remarks	

Note: Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ಇ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿ.ಬಿ.ಎಂ.ಪಿ
ಬೆಂಗಳೂರು-560073

Rajalakshmi Geo Consultants Bangalore

Scanned with CamScanner

RAJALAKSHMI GEO CONSULTANTS

Rukmini Nagar, Nagasandra, Tumkur road, Bangalore 560057
Mobile: 9986028766

DATE: 19/07/21

REPORT ON GROUND WATER INVESTIGATION

01. Name of the Party	**Executive Engineer, BBMP, Dasarahalli Division.**
02. Location of land/Site	w no 14 siddedahalli main road bayaraveswara circala near
03. Purpose of Ground Water	Drinking water
04. Area	Bagalagunte
05. Approximate Drilling Depth	370-390 rmt
06. Approximate Casing Pipe	55-65 rmt
07. PVC Pipe	20-25 rmt
08. Expected Yield	1500-2000 GPH
10. Remarks	

Note: Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ಜಿ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಜಿ.ಜಿ.ಎಂ.ಪಿ
ಬೆಂಗಳೂರು-560073

Rajalakshmi
Geo Consultants
Bangalore

Scanned with CamScanner

RAJALAKSHMI GEO CONSULTANTS

Rukmini Nagar, Nagasandra, Tumkur road, Bangalore 560057
Mobile: 9986028766

DATE: 19/07/21

REPORT ON GROUND WATER INVESTIGATION

01. Name of the Party	**Executive Engineer, BBMP, Dasarahalli Division.**
02. Location of land/Site	w no 14 bagalagunte 5 th cross siddeswara layout
03. Purpose of Ground Water	Drinking water
04. Area	Bagalagunte
05. Approximate Drilling Depth	385-405 rmt
06. Approximate Casing Pipe	55-70 rmt
07. PVC Pipe	20-25 rmt
08. Expected Yield	1500-1800 GPH
10. Remarks	

BE-4

Note: Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಜಿ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿ.ಬಿ.ಎಂ.ಪಿ
ಬೆಂಗಳೂರು-560073

Rajalakshmi Geo Consultants Bangalore

Scanned with CamScanner

RAJALAKSHMI GEO CONSULTANTS

Rukmini Nagar, Nagasandra, Tumkur road, Bangalore 560057
Mobile: 9986028766

DATE: 20/07/24

REPORT ON GROUND WATER INVESTIGATION

01. Name of the Party	**Executive Engineer, BBMP, Dasarahalli Division.**
02. Location of land/Site	w no 14 vishveshwaiah layout 5 th cross bagalagunte
03. Purpose of Ground Water	Drinking water
04. Area	Bagalagunte
05. Approximate Drilling Depth	370-380 rmt
06. Approximate Casing Pipe	50-60 rmt
07. PVC Pipe	20-25 rmt
08. Expected Yield	1500-2000 GPH
10. Remarks	

AE-14
29

Note: Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಜಿ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ. ಜಿ.ಜಿ.ಎಂ.ಪಿ
ಬೆಂಗಳೂರು-560073

Rajalakshmi Consultants Bangalore

Scanned with CamScanner

RAJALAKSHMI GEO CONSULTANTS

Rukmini Nagar, Nagasandra, Tumkur road, Bangalore 560057
Mobile: 9986028766

DATE: 20/07/21

REPORT ON GROUND WATER INVESTIGATION

01. Name of the Party	**Executive Engineer, BBMP, Dasarahalli Division.**
02. Location of land/Site	w no 14 vishveshwaiah layout 10 th cross bagalagunte
03. Purpose of Ground Water	Drinking water
04. Area	Bagalagunte
05. Approximate Drilling Depth	380-400 rmt
06. Approximate Casing Pipe	60-70 rmt
07. PVC Pipe	20-25 rmt
08. Expected Yield	2000-2500 GPH
10. Remarks	

Note: Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ಜಿ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿ.ಬಿ.ಎಂ.ಪಿ.
ಬೆಂಗಳೂರು-560073

Rajalakshmi Geo Consultants Bangalore

Scanned with CamScanner

RAJALAKSHMI GEO CONSULTANTS

Rukmini Nagar, Nagasandra, Tumkur road, Bangalore 560057
Mobile: 9986028766

REPORT ON GROUND WATER INVESTIGATION

DATE: 20/07/21

01. Name of the Party	**Executive Engineer, BBMP, Dasarahalli Division.**
02. Location of land/Site	w no 14 siddedahalli infront of siddeswara temple
03. Purpose of Ground Water	Drinking water
04. Area	Bagalagunte
05. Approximate Drilling Depth	380-400 rmt
06. Approximate Casing Pipe	50-60 rmt
07. PVC Pipe	20-25 rmt
08. Expected Yield	1600-2000 GPH
10. Remarks	

Note: Although the best site for drilling has been suggested. NO GUARANTEE of success can be given and we will not be liable in any way for any loss to the party in respect of the well drilled at the recommended being failure

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬಿ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಜಿ.ಜಿ.ಎಂ.ಪಿ
ಬೆಂಗಳೂರು-560073

Rajalakshmi Geo Consultants Bangalore

Scanned with CamScanner